



①



In this state, a magnet does not face each other.

② Turn piece in the way of a screw.



③ They come apart.



④



Combine piece from the reverse side of the place from which it come apart.

⑤ It will be the shape just like shown in below.



⑥ Turn piece in the way of a screw.



⑦ The magnet at a tip faces stick together, and it becomes a ring.

